

Release Notes

Product Name: TP-583Txr, TP-583Rxr

Current Version:

Type	Number	Date
Firmware	–	–
Software	–	–
Web	–	–
Hardware	–	January 2019

RN Date: January 14, 2019

Reference: 13276

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
TP-583Txr	N/A	N/A	N/A
TP-583Rxr	N/A	N/A	N/A

Technical Notes:

- This is a release note for new products.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: TP-583Txr, TP-583Rxr

Current Version:

Type	Number	Date
Firmware	–	–
Software	–	–
Web	–	–
Hardware	–	January 2019

RN Date: January 14, 2019

Reference: 13276

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/TP-583Txr>

The following changes were made in this version:

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
14607	IN LED illuminates when HDMI cable is connected without power to the input.
15220	For some matrix models, there may not be an output signal following extender power-up. Workaround: Disconnect and reconnect the HDMI cable.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com