Release Notes

Product Name: **VW-4**

Current Version:

Type	Number	Date
Firmware	1.11	July 2022
Software	–	–
Web	–	–
Hardware	–	–

RN Date: July 11, 2022
Reference: 00000

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VW-4	Any	Yes	Yes

Summary:

- Beta FW enables the selection of 1080p 50 or 1080p 60.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

Release Notes

Product Name: **VW-4**

Current Version:

Type	Number	Date
Firmware	1.11	July 2022
Software	–	–
Web	–	–
Hardware	–	–

RN Date: July 11, 2022

Reference: 00000

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
18468	Output HDCP now follows output when Follow Output is selected in the application.
19014	Power must be cycled after upgrading the firmware via K-Upload using RS-232

Preceding Version: 1.10

Release Notes History

Product Name: **VW-4**

Current Version:

Type	Number	Date
Firmware	1.10	March 2021
Software	–	–
Web	–	–
Hardware	–	–

RN Date: March 25, 2021

Reference: 17259

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VW-4	Any	Yes	Yes

Technical Notes:

- Fixed bugs.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

Release Notes History

Product Name: **VW-4**

Current Version:

Type	Number	Date
Firmware	1.10	March 2021
Software	–	–
Web	–	–
Hardware	–	–

RN Date: March 25, 2021

Reference: 17259

Bugs Fixed:

QC ID	Fixed Bug Description
19000	5V was active on the LOOP output after power up, even when the input was not connected.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
18468	Output HDCP now follows output when Follow Output is selected in the application.
19014	Power must be cycled after upgrading the firmware via K-Upload using RS-232

Preceding Version: 1.09

Release Notes History

Product Name: **VW-4**

Current Version:

Type	Number	Date
Firmware	1.09	January 2021
Software	–	–
Web	–	–
Hardware	–	–

RN Date: January 4, 2021
Reference: 08067

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VW-4	N/A	N/A	N/A

Technical Notes:

- This is a release note for a new product.

Release Notes History

Product Name: VW-4

Current Version:

Type	Number	Date
Firmware	1.09	January 2021
Software	–	–
Web	–	–
Hardware	–	–

RN Date: January 4, 2021
Reference: 08067

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/VW-4

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
18468	Output HDCP always follows the input, even if Follow Output is selected in the application

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
19014	Power must be cycled after upgrading the firmware via K-Upload using RS-232

Preceding Version: N/A