



**Product Name:** FC-26, K-Touch Starter Kit

<b>Current Version:</b>	<b>Ver.Type</b>	<b>Ver No.</b>	<b>Date</b>
	<b>Firmware</b>	2.8.30857	November 2016
	<b>Software</b>	–	–
	<b>Web</b>	–	–
	<b>Hardware</b>	–	–

**RN Date:** November 2016

**Reference:** 11509

### Kramer Product Affected:

<b>Product Name</b>	<b>Minimum FW Version for Upgrade</b>	<b>Recommended for All Units</b>	<b>Only if Added Features are Required</b>
FC-26	Any	Yes	N/A
K-Touch Starter Kit	Any	Yes	N/A

### Technical Notes:

- Support was added for a new flash device. There is no change in functionality. The new firmware works both with the new and the old chipsets.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerel.com](mailto:info@kramerel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** FC-26, K-Touch Starter Kit

**Current Version:**

Ver.Type	Ver No.	Date
Firmware	2.8.30857	November 2016
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** November 2016

**Reference:** 11509

The following changes were made in this version:

**New Features:**

	Description
	Added support for new flash device

**Bugs to be Fixed in Future Version:**

QC ID	Description
6715	WEB GUI: IR command name includes only 15 chars
7354	WEB GUI: IR Learning appends an extra "space" char to command string
8557	Incorrect device serial mode is presented on Web page
9151	Incorrect time validation
9156	Model command wrong results after factory reset

**Known Limitations (including compatibility limitations):**

QC ID	Description
5845	WEB Log tab – Serial transferred data is not shown
5846	WEB GUI: "Discard changes" warning message is not shown when changing the 'Send replies to new client by default' button
6615	No IR learning LED exists
6627	Device control operation is ceased during IR learning process
6841	IE11: Save Configuration process is not supported
9160	Device IP address is not changed upon DHCP change from ON to OFF
9127	Default UDP port 50000 is always open

**Preceding Version:** F – 1.11.24319



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** FC-26, K-Touch Starter Kit  
**Preceding Version:** F – 1.11.24319  
**Version Date:** December 2015  
**Reference:** 9638

The following changes were made in this version:

### Added Features:

- IR learning added.
- Default hostname and TCP ports

### Bugs to be Fixed in Future Version:

QC ID	Description
4985	WEB: Unable to change the UDP/TCP value of ETH port
5001	Incorrect response for P3K Reset command
5002	P3K NAME-RST command doesn't work
5004	Unable to set a password that includes letters by P3K Pass command
5005	Incorrect response for P3K Factory command
5008	Factory reset command resets a model name for default one
5024	WEB: No Factory reset option
5033	Unable to configure a serial port device for 1200-4800 baud rates
5038	WEB: No scroll option
5039	WEB: Unrecognized error message during tunneling creation
5845	WEB GUI: Log tab - Data transfer is not appear
5846	WEB GUI: Add a "Discard changes" warning message when changing the 'Send replies to new client by default' button
5915	It is possible to set TCP port value less than 1024
6841	IE11: Unable to perform Save Configuration process
6914	Wrong web page message of "You must use internet explorer 9 or higher..." as it works with release 10 or higher only



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerelect.com](mailto:info@kramerelect.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



---

## Known Issues:

- There are no known issues.

**Preceding Version:** F – 1.1.22038



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerel.com](mailto:info@kramerel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** FC-26, K-Touch Starter Kit  
**Preceding Version:** F – 1.1.22038  
**Version Date:** August 2015  
**Reference:** 9281

The following changes were made in this version:

**Added Features:**

- FC-26 was integrated with K-Touch.

**Fixes:**

- Bugs were fixed.

**Known Issues:**

- There are no known issues.

**Preceding Version:** F – 1.1.21320



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** FC-26  
**Preceding Version:** F – 1.1.21320  
**Version Date:** July 2015  
**Reference:** 9161

The following changes were made in this version:

**Fixes:**

- Tunneling bugs were fixed.

**Modifications:**

- DHCP default setting is ON.

**Known Issues:**

- There are no known issues.

**Preceding Version:** NP – 1.0



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramere.com](mailto:info@kramere.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** FC-26  
**Preceding Version:** NP – 1.0  
**Version Date:** May 2015  
**Reference:** 6653

This is a release note for a new product.

**Known Issues:**

- There are no known issues.

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramere.com](mailto:info@kramere.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)