# **KRAMER ELECTRONICS RELEASE NOTE**



Product Name:	TP-580T, TP-580	OR	
<b>Current Version:</b>	F – 2.31.00 (Valens)		
Version Date:	December 2015		
Reference:	9197		
Release Type:			
Firmware	Software	Hardware	New Product

## Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
TP-580T	Any	Yes	N/A
TP-580R	Any	Yes	N/A

## **Technical Notes:**

- A missing video problem was fixed.
- This upgrade can be done only in the Kramer office. Please contact your Kramer dealer for details.

## **Codependency with Other Products and Software:**

• There is no codependency with other products or software.





Product Name:	TP-580T, TP-580R
<b>Current Version:</b>	F – 2.31.00 (Valens)
Version Date:	December 2015
Reference:	9197

The following changes were made in this version:

### Fixes:

• On some screens, video is missing with certain resolutions (for example, XGA on some Dell monitors).

### **Known Issues:**

• There are no known issues.

Preceding Version: F – 2.30.90 (Valens)





 Product Name:
 TP-580T, TP-580R

 Preceding Version:
 F - 2.30.90 (Valens)

 Version Date:
 July 2014

 Reference:
 7604

The following changes were made in this version:

#### Fixes:

• When the transmitter and receiver were powered up together, the monitor did not always receive video.

#### Known Issues:

• There are no known issues.

Preceding Version: NP - 1.0





Product Name:	TP-580T, TP-580R
<b>Current Version:</b>	NP – 1.0
Version Date:	April 2013
Reference:	2499

This is a release note for a new product.

• Kramer strongly recommends using shielded cable with this product.

### **Known Issues:**

• There are no known issues.

Preceding Version: N/A

