

## Release Notes

**Product Name:** vm-2h2, VM-3H2, VM-4H2

**Current Version:**

Type	Number	Date
Firmware	R1.3.62415	February 2022
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** February 6, 2022

**Reference:** 18019, 18020, 18021

### Kramer Products Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VM-2H2vm-2h2	Any	Yes	Yes
VM-3H2	Any	Yes	Yes
VM-4H2	Any	Yes	Yes

### Summary:

- Bug fix
- New firmware

### Codependency with Other Products and Software:

- There is no codependency with other products or software.

### Bugs Fixed:

ID	Fixed Bug Description
<a href="#">KMR-80827</a>	For HDCP 2.2 source, when all four outputs are connected to 4 HDCP2.2 sinks, the video output fails for all four or some of the outputs.

### Known Limitations (including compatibility limitations):

ID	Limitation Description
	None listed

**Preceding Version:** R1.2.28549



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)