



## **Release Note**

Product Name: VM-4HDT

Current Version: | Ver.Type | Ver No. | Date

 Firmware
 4.0.40281
 August 2017

 Software

 Web

 Hardware

RN Date: August 2017

Reference: 10904

#### **Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VM-4HDT	Any	Yes	N/A

#### **Technical Notes:**

• HDCP, EDID and video display issues fixed.

### **Codependency with Other Products and Software:**

There is no codependency with other products or software.

KRAMER ELECTRONICS, Ltd.





# **Release Note**

Product Name: VM-4HDT

Current Version: Ver.Type Ver No. Date

 Firmware
 4.0.40281
 August 2017

 Software

 Web

 Hardware

RN Date: August 2017

Reference: 10904

The following changes were made in this version:

## **Bugs Fixed:**

QC ID	Fixed Bug Description		
	HDCP ON / OFF handling improvements		
5668	Properly encrypted video signal display on specific AV sink devices		
5681	Proper audio extension handling on specific TV devices		
5695	Mixed EDID feature disabled		
5729	No indication of default EDID loaded to input		
	HDCP process in 1080p@24Hzx & 4k@24Hzx fix		
8504, 8530	Fixes for video display flickering occurring during some sources switching scenarios		
8586	Encrypted signal plug in/out flickering display fix		
10740	Corrupted EDID in the input after copy		
10741	Fixed rare occurrence of unit getting stuck following EDID copy action		
10793	Fixed occurrence of unit getting stuck following Get EDID action		
10929	No video display following power ON/OFF of specific TV types		
11692	Video display no longer flashes for 1 second when the first output is connected after unit power up		

KRAMER ELECTRONICS, Ltd.





# **Release Note**

## **Bugs to Fix in Future Versions:**

QC ID	Deferred Bug Description
10943	Very rarely, HDCP input fails after power up
15820	When either directly connected to source or via VM-4HDT DA, signal display may be lost upon switching between HDCP and non-HDCP sources, for a few specific display models.  Workaround: Replug input connection.

## **Known Limitations (including compatibility limitations):**

None listed.

**Preceding Version:** NP - 1.0



KRAMER ELECTRONICS, Ltd.





# **Release Note History**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units		Only if Added Features are Required		
Kramer Product Affected:						
Release Type:  Firmware	☐ Software	☐ Hardware		New Product		
Reference:	7854					
Version Date:	February 2016					
<b>Current Version:</b>	NP - 1.0					
Product Name:	VM-4HDT					

N/A

N/A

### **Technical Notes:**

VM-4HDT

• This is a release note for a new product.

N/A

## **Codependency with Other Products and Software:**

• There is no codependency with other products or software.

•



KRAMER ELECTRONICS, Ltd.





# **Release Note History**

**Product Name**: VM-4HDT

**Current Version:** NP - 1.0

Version Date: December 2015

Reference: 7854

This is a release note for a new product.

#### **Known Issues:**

• There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.